

A REPORT ON THE BEHAVIOUR OF STRUCTURES EMPLOYING PRESTRESSED CONCRETE DURING NIIGATA EARTHQUAKE

Dr. Shunji Inomata*

Structures employing prestressed concrete are being designed more and more in Japan. However, until the earthquake in Niigata on 16th June 1964, little actual experience has been recorded about performance of prestressed concrete during a quake. Report has placed the epicenter between 45 and 50 km off the coast of Niigata City and a depth of 20 km. The magnitude was 7.7 on the Richterscale.

The map of Niigata Prefecture and location of the epicenter is shown in Fig. 1.

Niigata City is situated on the north-west shore of Japan, the subsoil seems to be sand and silty sand to a depth of 120 m under much of the city. This is a possible explanation for the magnitude of the


damage in Niigata City. Groundwater is generally close to the surface. The newer portion of the city is built alongside the Shinano River, and some areas are below sea level and are protected by an embankment. Apart from coastal sand dunes the area is generally very flat. During the earthquake, large volumes of water and fine sand gushed up through fissures which appeared in the ground. This water was not from the many broken pipes, but was of subterranean origin.

In the area near to the Shinano River, there was extensive and irregular subsidence. The maximum subsidence was probably about 1.8 m. Apart from damage caused by a landslide in the coastal dunes, the main damage was in the subsidence area.

Failure of foundation materials did damage many commercial buildings, apartments, houses and some schools. In most cases, such damage occurred to structures located near the Shinano River and weak soil deposit, liquification or consolidation of weak sand or soil deposit, possibly in an old stream channel, apparently caused this slump.

Damage due to the earthquake may be divided into two groups, that is damages come about as a result of extensive subsidence or landslide and vibration. In Niigata city the damage due to this vibration was observed on the buildings which were built on coastal sand dunes, but this type of damage was not serious. Serious damage due to extensive subsidence caused by the earthquake was observed on all the buildings in the city. Many large raft founded or even, pile founded buildings simply tilted over or subsided, but most of these buildings remain structurally sound. This type of tilt and subsidence should occur so gradually that static force should act on these buildings. Fig. 2 and Fig. 3 show those types of damage. All the reinforced concrete buildings which have been designed and executed through the provisions of Japanese building code, have not shown any structural damage at all and were not cracked.

Fig. 1 Niigata prefecture



* Secretariat, Japan Prestressed Concrete Engineering Association.

seriously even in case of slump or tilt.

One large steel bridge girders fell into the Shinano River due to the extensive subsidence of steel bent founded on steel piles and the girder of adjacent four span pulled off the steel bents and collapsed over the river (Fig. 4).

Unfortunately the main fault or subsidence area occurred through the centre of Niigata City, as would be expected no structures could withstand this type of displacement (Fig. 5).

Aside from Niigata City there were not observed so extensive subsidence as to give serious damage to the structures.

1. Structures employing prestressed concrete in Niigata prefecture

More than 68 prestressed concrete structures were built in Niigata prefecture and of the 68 structures employing prestressed concrete, seven of these were in Niigata City and the other structures were distributed all over Niigata prefecture. Of the 68 structures, one of these was canopy of Niigata Railway station and the other 67 structures were bridges. All these bridges were simply supported structures and have suffered no serious damages at all.

Apart from minor spalling of concrete over the abutments or piers at bearing level and deck level, the prestressed portion of the structure was undamaged. The severe damages of this kind were observed only in Niigata City and on the outskirts of the city. The structures which were in Niigata City will be discussed at length later.

Typical distress conditions observed on the prestressed concrete simply supported bridges may be summarized as follows.

- 1) Instances of hammering of the end of girder against each other were observed and spalling of concrete at the end of girder was observed (Fig. 6, 7, 8).
- 2) Vertical and horizontal cracking was frequently visible on the top face concrete of abutment or pier where bearing of prestressed concrete girder was connected to it by shear dowels (Fig. 9, 10, 11).
- 3) Hammering of concrete movable rocker bearing against the wall of the hole where the rocker bearing was placed. Cracking of concrete of abutment or pier was frequently visible. The earthquake emphasized again that the structures should be properly spaced or jointed to prevent

hammering of adjacent parts (Fig. 12).

- 4) Rubberpad bearing deformed extensively during the earthquake and did not recover the original position (Fig. 13).
- 5) Abutment and pier shifted or tilted, apparently due to liquidaion of weak sandy and silty foundation materials.
- 6) Cracking and sometimes crushing of concrete was observed on the wingwall of abutment.

Customary practice in Japan is to provide direct mechanical connection between one end of girder and abutment or pier without restraining rotational movement but restraining horizontal movement. The girders are seated on bearings and connected also to the pier caps by shear dowels which are embedded into the concrete of caps. The other end of the girder must be allowed to the horizontal and rotational movements due to temperature, shrinkage effects and to shortening of the components under prestress. At the fixed end of girder, bearing apparatus is usually connected to the support concrete with the embedded bolts. Cross-sectional area of this bolt is commonly calculated so as to be able to resist to the shearing force due to earthquake. Shearing force acting to this bolt during earthquake is assumed to be equal to the total dead weight of girder multiplied by seismic coefficient. The seismic coefficient shall be determined in accordance with regional earthquake activity. Usually this coefficient is assumed to be equal to 0.2.

Design codes for earthquake-resistant shear dowels have used allowable design stresses 70% greater than normal design stresses. Allowable design shearing stress for mild steel is equal to 600 kg/cm².

No damages, for example shearing off the bolts, have been observed on all the prestressed concrete bridges and also no falling down of girders has been observed. But in the absence of any suitable cover of concrete to the embedded bolts or appropriate arrangement of mild-steel bars around the pier cap and bolts, the concrete cover has been destroyed due to the horizontal movement of bolt. Sometimes the pull-out of the bolt has been observed in the absence of insufficient length of embedded bolt (Fig. 14).

It has always been considered that forces of seismic origin should be transmitted by the most direct path. A procedure of using linkage bolts and rubber buffers connected through the adjacent end diaphragms of each span in case of simply supported

prestressed concrete constructions will be adequate. This design could reduce the risk of damage due to adjacent spans moving out of phase in earthquake, as well as to transmit the forces to the anchorages in a direct path. Even in this case, special attention should be placed on the design and placing the shear dowels.

Details of shear dowels can handle seismic problems by proper attention to structural investigations and adopting good design practices. In seismic areas it is particularly important that all the requirements of plans and specifications be observed meticulously and that all workmanship be of high quality, because the possibility of earthquake damage is greatly increased by any construction deficiencies.

2. Structures employing prestressed concrete in Niigata City

Of the seven structures employing prestressed concrete in Niigata City, four bridges used pre-tensioned standard pre-cast beams employing bonded transverse post-tensioned tendons and two were post-tensioned bridges employing bonded post-tensioned precast girders assembled by transverse prestressing and one was a entire canopy or verandah, over the foyer employing pre-tensioned members on precast columns and beams assembled with mortar joints.

The following report is chiefly concerned to those seven structures located in Niigata City where the main fault or subsidence has occurred.

(1) Teiseki Bridge

This bridge is 272 m long with 6 m carriageway with 13 spans over the Shinano River. The piers were cast in situ on precast concrete piles. The deck is consisted of pre-cast beams post-tensioned longitudinally and transversely through the deck and the diaphragms. All tendons are fully grouted and bonded. All beams are adequately connected to the piers against horizontal forces with shear dowels. Despite considerable displacement of the foundations and possibly of the river bed, the bridge has suffered no visible damage at all. It is interesting to see that several of the central spans of an adjacent steel pipe bridge have collapsed and are leaning against the undamaged prestressed bridge (Fig. 15).

(2) Higashikosen-Bridge

This bridge has a structural steel centre span with the approach spans consisting of pre-tensioned standard beams with cast-in-situ diaphragms and deck prestressed by transverse tendons. This approach bridge

is 203 m long with 8.00 m carriageway, with 15 spans. Beams were supported on reinforced concrete portal frames. There was considerable movement of the piers, some of which moved from 1 cm to 30 cm vertically relative to one another, and horizontally by as much as 40 cm at the top. Because the center steel span was not properly secured, it pulled off the supports and collapsed over the national railway line (Fig. 16). Apart from minor spalling over the piers at deck level, the prestressed portion of the structure was undamaged (Fig. 17, 18, 19)

(3) Yachiyo Bridge

This bridge has structural steel main spans over the Shinano River with approach two spans consisting of pre-tensioned standard beams with cast-in-situ concrete prestressed by transverse tendons. This approach bridge has two span of 7.5 m long each with 8.5 m carriageway. There was considerable movement of the piers, some of which moved by 30 cm vertically and also extensive subsidence of the approach embankment was observed (Fig. 20). Due to this extensive subsidence and the vibration during the quake, piers simply tilted over as shown in Fig. 21 and Fig. 22 and spalling of concrete at the end of beams was observed.

(4) Ōrai Bridge

The bridge has an overall length of 63.0 m with five equal spans. The bridge provides 5.5 m wide carriageway and is consisted of pre-tensioned standard beams with cast-in-situ concrete prestressed by transverse tendons. Second pier subsided by about 4 cm but no damage was observed in the prestressed portion of the structure. But horizontal and vertical cracking of wing wall of abutment was visible (Fig. 23).

(5) Sasagoshi Bridge

The bridge has an overall length of 56.0 m with five equal spans, providing 9.5 m wide carriageway. The deck is consisted of pre-tensioned standard beams with cast-in-situ concrete prestressed by transverse tendons. Extensive subsidence of approach road surface was observed but the structure was undamaged at all (Fig. 24).

(6) Tūsengawa Bridge

This bridge is 15.0 m long with 7.70 m carriageway and the deck is consisted of cast-in-situ concrete slab post-tensioned longitudinally. One abutment slid forward and tipped over backward during earthquake (Fig. 25), but the prestressed concrete slab was undamaged.

The main part of this structure (18 spans of 5 m length each) is founded on precast concrete piles but the annex (3 spans of 6 m length each) is founded on soil-cement foundation. The foundation material (very fine sand) is apparently appears to have subsided by about 50 cm during earthquake (**Fig. 27**). The structure founded on concrete piles has withstood the movement extremely well and no damage could be observed in the prestressed members. But the structure which was not founded on concrete piles has subsided by about 35 cm relative to the main part of the structure.

Because of this difference of subsidence between two parts, the frame of first one span in the annex was subjected to unequal settlement of column and the ends of beam and the cantilever beam were partially cracked and also crushed (**Fig. 28, 29**). The prestressed concrete roof member was also damaged on the cracked column. But no damage could be observed on the end two spans of the annex.

This damage is apparently caused by difference of extensive and irregular subsidence of the foundations between two parts.

It is believed that Niigata earthquake can solve seismic problems by proper attention to foundation investigations and adopting good structural design

practices. Structural damage shows, on the part of designers, a lack of sensitivity to the foundation on sandy or silty subsoil. Designer must pay more attention to the fact that liquification or consolidation of weak sand or soil deposit could cause extensive subsidence during earthquake.

The anchor bolts holding the bearing plates into the piers or abutments tended to pull out of the thin covered concrete and cracked the concrete. In many cases the anchor bolts pushed the concrete cover and made it cracked. It would appear that this failure of the concrete could have been overcome if adequate mild steel had been provided around the anchor bolts. Furthermore it was evident that the thickness of concrete covering was not sufficient to resist to the horizontal pulling force of the anchor bolts. It is not able to discover the exact design method to which the anchor bolt should be designed but it would appear that the existing shear dowels would not have sufficient strength as a whole.

Acknowledgments

The material presented in this paper is based on part of the report written by following contractors.

Oriental Concrete K.K.; Tajima Kogyo K.K.; P S Concrete K.K.; P C Bridge K.K.; Hotsukaido P S Concrete K.K.; Kowa Concrete K.K.; Sumitomo Kensetsu K.K.



Fig. 2 Reinforced concrete building tilted over and subsided




Fig. 3 4 story reinforced concrete building tipped down



Fig. 4 Steel bridge fell into the Shinano River (Shin-Showa Bridge)



Fig. 5 Extensive subsidence of embankment of Shin-Showa Bridge

Fig. 6 Hammering of the end of beam against each other. Spalling of concrete at bottom of beam.
(Shiroyama Bridge)
Overall length..... 120 m (4×30 m)
(Pcst-tensioned)
Width of carriage-way.....5.5 m





Fig. 7 Spalling of concrete at top of hand-railpost (Shiroyama Bridge)






Fig. 10 Cracking of abutment (Komatagawa Bridge) (Post-tensioned)
 All-Over length.....50.0 m (2×24.96 m)
 Width of Carriageway.....5.5 m





Fig. 11 Cracking of abutment (Komatagawa Bridge)



← **Fig. 8** Cracking of Concrete at deck level (Yasuda Bridge) (Post-tensioned)
 Over-all length.....825 m (23×25.80 m)
 Width of carriageway.....6.00 m

Fig. 12 Hammering of concrete movable rocker bearing against wall of hole caused cracking of concrete pier (Yasuda Bridge)





Fig. 13 Rubber pad bearing tilted over (Kosaka Bridge) (post-tensioned) Over-all length.....60.50 m (2×30.20 m) Width of carriageway.....6.0 m



← **Fig. 9** Cracking is visible on the top face concrete of pier (Yasuda Bridge)





Fig. 14 Pull-out of anchor bolt (Yasuda Bridge)






Fig. 15 Teiseki Bridge



Fig. 17 Spalling of concrete at deck level





Fig. 16 Center steel span pulled off the support and collapsed over National Railway Line



Fig. 18 Side view of approach span



Fig. 19 General view of deck surface



←
Fig. 20 Side view of embankment




Fig. 21 Pier tilted over




Fig. 22 Pier tilted over and spalling of concrete is visible




Fig. 25 One abutment tipped over




Fig. 23 Cracking of wing-wall



Fig. 27 Subsidence of foundation material




Fig. 28 Top view of failed members




Fig. 24 Extensive subsidence of approach road is observed





Fig. 29 Top view of difference of subsidence between main part and annex part

NCS-PCパイイル

プレテンション方式——NCS溶接継手



NCS-PCパイイルの特長

- ① 継手—全強であるから支持力の低減が要らない。
- ② 耐 撃 性—頭部が耐撃的であるため確実に打止りが得られる。
よって支持力に全材強を活用できる。
- ③ 曲げ剛性—プレストレスの効果によって曲げ剛性が大きい。
よってパイイル施工中の安全はもちろん、
くい基礎の経済設計ができる。



日本コンクリート工業株式会社

本 社 東京都中央区銀座東 8-19
営業所 大阪市阿倍野区天王寺町南 2 の 6 6
〃 名古屋市中村区下広井町 1 の 66 (三建設備工業ビル)
工 場 川 島 (茨城県下館市)
〃 鈴 鹿 (三重県鈴鹿市)
研 究 室 茨城県下館市川島工場内

電 話 東京 (542) 大代表 3151
電 話 大阪 (741) 3888・5003
電 話 名古屋 (54) 5918・5938
電 話 下館 2181~4
電 話 庄野 177・277
電 話 下館 3942